



Logbook Photo #	SDC10033
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	NW
Date	10/15/14
Time	0853 hrs
Photographer	J. Sherrard (START)
Witness	N. Biscocho (START)
Description:	
Current condition of the buried barge associated with the alkyne storage tank pump house.	
Southeast corner of the alkyne storage tank pump house facing northwest toward the barge slip inlet.	



Logbook Photo #	SDC10013
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	N
Date	10/15/14
Time	0820 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description: Current condition of the buried barge associated with the alkyne storage tank pump house. East wall of the alkyne storage tank pump house facing west toward the barge slip inlet.	



Logbook Photo #	SDC10035
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	N
Date	10/15/14
Time	0853 hrs
Photographer	J. Sherrard (START)
Witness	N. Biscocho (START)
Description:	<p>Hatch on the east wall of the alkyne storage tank pump house visible on the buried barge.</p> <p>Stained soils observed around the hatch and along the east wall of the alkyne storage tank pump house.</p>



Logbook Photo #	SDC10015
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	SW
Date	10/15/14
Time	0820 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description:	<p>Current condition of the alkyne storage tank pump house visible on the buried barge.</p> <p>East wall of the alkyne storage tank pump house facing southwest. Stained soils observed.</p>



Logbook Photo #	SDC10016
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	W
Date	10/15/14
Time	0821 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description: Current condition of the alkyne storage tank pump house visible on the buried barge. North wall of the alkyne storage tank pump house facing west.	



Logbook Photo #	SDC10017
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	W
Date	10/15/14
Time	0821 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description:	<p>Current condition of the alkyne storage tank pump house visible on the buried barge.</p> <p>North wall of the alkyne storage tank pump house facing west. Stained soils observed.</p>



Logbook Photo #	SDC10019
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	S
Date	10/15/14
Time	0822 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description:	<p>Hatch on the buried barge along the north wall of the associated alkyne storage tank pump house.</p> <p>Stained soils observed around the hatch and along the north wall of the alkyne storage tank pump house.</p>



Logbook Photo #	SDC10020
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	SW
Date	10/15/14
Time	0822 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description:	<p>Current condition of the alkyne storage tank pump house visible on the buried barge.</p> <p>North wall of the alkyne storage tank pump house facing southwest.</p>



Logbook Photo #	SDC10043
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	NE
Date	10/15/14
Time	0855 hrs
Photographer	J. Sherrard (START)
Witness	N. Biscocho (START)
Description: Current condition of the alkyne storage tank pump house visible on the buried barge. South wall of the alkyne storage tank pump house facing northwest.	



Logbook Photo #	SDC10009
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	NW
Date	10/15/14
Time	0819 Hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description:	
View inside the alkyne storage tank pump house visible on the buried barge, facing northwest.	
Water and oil mixture observed in the interior of the alkyne storage tank pump house structure.	



Logbook Photo #	SDC10010
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	N
Date	10/15/14
Time	0819 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description:	<p>View inside the alkyne storage tank pump house visible on the buried barge, facing north.</p> <p>Water and oil mixture observed in the interior of the alkyne storage tank pump house structure.</p>



Logbook Photo #	SDC10011
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	NE
Date	10/15/14
Time	0819 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description: View inside the alkyne storage tank pump house visible on the buried barge, facing northeast. Water and oil mixture observed in the interior of the alkyne storage tank pump house structure.	



Logbook Photo #	SDC10012
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	E
Date	10/15/14
Time	0819 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description:	<p>View inside the alkyne storage tank pump house visible on the buried barge, facing east.</p> <p>Water and oil mixture observed in the interior of the alkyne storage tank pump house structure.</p>



Logbook Photo #	SDC10034
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	N
Date	10/15/14
Time	0853 hrs
Photographer	J. Sherrard (START)
Witness	N. Biscocho (START)
Description:	
Stained soil from the buried barge associated with the alkyne storage tank pump house.	
Stained soil observed adjacent to the above ground storage tank (AST) on the east side of the alkyne storage tank pump house.	



Logbook Photo #	SDC10036
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	SE
Date	10/15/14
Time	0853 hrs
Photographer	J. Sherrard (START)
Witness	N. Biscocho (START)
Description: Stained soil from the buried barge associated with the alkyne storage tank pump house. Looking southeast stained soil observed from the alkyne storage tank pump house, along the south side of the structure, to the drain ditch adjacent to the wetland.	



Logbook Photo #	SDC10030
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	NE
Date	10/15/14
Time	0852 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description: Overview of the site surrounding the buried barge associated with the alkyne storage tank pump house. Barge slip located north of the alkyne storage tank pump house.	



Logbook Photo #	SDC10031
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	SW
Date	10/15/14
Time	0853 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description: Overview of the site surrounding the buried barge associated with the alkyne storage tank pump house. Facing south from the alkyne storage tank pump house.	



Logbook Photo #	SDC10044
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	E
Date	10/15/14
Time	0855 hrs
Photographer	J. Sherrard (START)
Witness	N. Biscocho (START)
Description: Overview of site surrounding the buried barge associated with the alkyne storage tank pump house. Facing east toward the buried barge.	



Logbook Photo #	SDC10022
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	W
Date	10/15/14
Time	0851 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description: (Photo 1 of 4 from SBA-RA-01) View of sample location SBA-RA-01 located on the north side of the buried barge associated with the alkyne storage tank pump house. Facing southwest at sample location SBA-RA-01.	



Logbook Photo #	SDC10025
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	SE
Date	10/15/14
Time	0852 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description: (Photo 2 of 4 from SBA-RA-01) View of sample location SBA-RA-01 located on the north side of the buried barge associated with the alkyne storage tank pump house. Facing southeast at sample location SBA-RA-01.	



Logbook Photo #	SDC10021
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	W
Date	10/15/14
Time	0832 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description: (Photo 3 of 4 from SBA-RA-01) START collecting sediment sample from SBA-RA-01 along the north wall of the buried barge associated with the alkyne storage tank pump house. SBA-RA-01 sample: black in color; hydrocarbon odor; oil/grease sludge nature.	



Logbook Photo #	SDC10023
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	W
Date	10/15/14
Time	0851 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description: (Photo 4 of 4 from SBA-RA-01) Collected sediment sample from SBA-RA-01 along the north wall of the buried barge associated with the alkyne storage tank pump house.	



Logbook Photo #	SDC10009
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	NW
Date	10/15/14
Time	0819 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description: (Photo 1 of 2 from SBA-RA-02) View of sample location SBA-RA-02 inside the alkyne storage tank pump house visible on the buried barge. Facing northeast at sample location SBA-RA-01.	



Logbook Photo #	SDC10045
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	NW
Date	10/15/14
Time	0900 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description: (Photo 2 of 2 from SBA-RA-02) START collecting sediment sample from SBA-RA-02 inside the alkyne storage tank pump house visible on the buried barge. SBA-RA-01 sample: oil/water mixtures, black oil and clear water; hydrocarbon odor;	



Logbook Photo #	SDC10047
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	W
Date	10/15/14
Time	0928 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description: (Photo 1 of 2 from SBA-RA-03) View of sample location SBA-RA-03 located to the northwest of the buried barge associated with the alkyne storage tank pump house.	



Logbook Photo #	SDC10048
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	NW
Date	10/15/14
Time	0928 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description: (Photo 2 of 2 from SBA-RA-03) View of sample location SBA-RA-03 adjacent to the horizontal saddle tank northwest of the buried barge associated with the alkyne storage tank pump house. Facing northwest at sample location SBA-RA-03. SBA-RA-03 sample: clear and odorless.	



Logbook Photo #	SDC10046
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	NW
Date	10/15/14
Time	0925 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description: START collecting depth of buried barge from the hatch opening along the east wall of the associated alkyne storage tank pump house. Depth of buried barge is approximately 7.6 feet.	



Logbook Photo #	SDC10049
US EPA ID / Task Order Number	CERCLIS No. LAD008434185 / 2/Dynamac-077-15-001
Site	SBA Shipyard, Inc. – Removal Assessment (RA)
Location Address	9040 Castex Landing Road
City, State	Jennings, Louisiana
Parish	Jefferson Davis
Direction/Orientation	S
Date	10/15/14
Time	1006 hrs
Photographer	N. Biscocho (START)
Witness	J. Sherrard (START)
Description:	
SBA site secured/locked prior to demobilizing from Jennings, LA	